## LABOR SERVICES DIVISION[875]

## **Adopted and Filed**

Pursuant to the authority of Iowa Code section 89A.3, the Elevator Safety Board hereby amends Chapter 73, "Conveyances Installed Prior to January 1, 1975," Iowa Administrative Code.

This amendment requires that owners retrofit certain elevators to ensure safe access to the machine's governor for elevator inspectors and mechanics.

The purpose of this amendment is to protect the health and safety of the public and implement legislative intent.

Notice of Intended Action was published in the March 24, 2010, Iowa Administrative Bulletin as **ARC 8623B**. No public comment was received on the proposed amendment. This amendment is identical to the amendment that was published under Notice of Intended Action.

No variance provisions are included in these rules. Variances procedures are set forth in 875—Chapter 66.

This amendment is intended to implement Iowa Code chapter 89A.

This amendment shall become effective on June 23, 2010.

The following amendment is adopted.

Adopt the following **new** subrule 73.14(9):

**73.14(9)** Access to a governor that is located inside a hoistway shall be provided in accordance with ASME A17.1-2007, Rule 2.7.6.3.4.

[Filed 4/29/10, effective 6/23/10] [Published 5/19/10]

EDITOR'S NOTE: For replacement pages for IAC, see IAC Supplement 5/19/10.